





COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 1 of 11












FIG. 5

COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 6 of 11




FIG. 6




FIG. 7

COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 7 of 11




FIG. 8




FIG. 9

COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 8 of 11






FIG. 10



COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 9 of 11







FIG. 14

COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 10 of 11



COMPRESSOR ASSEMBLY HAVING BAFFLE Robin G. Skinner et al. / TEC1253-01 / Serial No. 10/657,652 Sheet 11 of 11

